



[Forum: 8-bit PIC](#)

[Topic: MCP2221DLL SmbReadBlock 讀不到資料](#)

[Subject: Re: MCP2221DLL SmbReadBlock 讀不到資料](#)

作者: Edison_yu

2018年01月03日 09:11:37

4.2.5 SMBDAT low timeout

It is possible that a malfunctioning device holds the SMBDAT line low indefinitely. This would prevent the master from issuing a STOP condition and ending a transaction. At this time there is no specification on the maximum time that a device can hold SMBDAT low after the master raises SMBCLK after the last bit of a transaction. Such a specification is under consideration for future revisions of the SMBus specification. In the meantime, the recommendation is that if SMBDAT is still low $t_{\text{TIMEOUT,MAX}}$ after SMBCLK has gone high at the end of a transaction the master should hold SMBCLK low for at least $t_{\text{TIMEOUT,MAX}}$ in an attempt to reset the SMBus interface of all of the devices on the bus.