

您設計產品時的好朋友！



[Forum: 32-bit PIC](#)

Topic: PIC32MM 出現 Configuration mismatch reset

Subject: Re: PIC32MM 出現 Configuration mismatch reset

作者: Ryang

2018年07月19日 10:42:54

32.2.1.1 CONFIGURATION REGISTER PROTECTION

To ensure the 128-bit data integrity of each Configuration Word, a comparison is continuously made between each Configuration bit and its stored complement. If a mismatch is detected, a Configuration Mismatch Reset is generated causing a device Reset.