

您設計產品時的好朋友！



Forum: [8-bit PIC](#)

Topic: [16F18323 bootloader](#)

Subject: [Re: 16F18323 bootloader](#)

作者: [GodBlessU](#)

2018年07月31日 23:26:57

我有收到您的e-mail了~ 不過因為是我私人的信箱，所以我將您的錯誤訊息貼在板上。

請您先安裝最新版的Bootloader Library v2.2.31與最新的MCC v3.55.1與PIC10 / PIC12 / PIC16 / PIC18 MCUs的peripheral library，應該有解掉此BUG。

請到下面網站下載，

<http://www.microchip.com/mp/lab/mp/lab-code-configurator>

附加檔案：

Bootloader Error Message.jpg(98.35 KB)

```
make -f nbproject/Makefile-default.mk SUBPROJECTS= build-conf
make[1]: Entering directory 'D:/bootloader/16f18323bootloader.X'
make -f nbproject/Makefile-default.mk dist/default/production/16f18323bootloader.X.production.hex
make[2]: Entering directory 'D:/bootloader/16f18323bootloader.X'
"C:\Program Files (x86)\Microchip\xc8\v1.41\bin\xc8.exe" --pass1 --chip=16F18323 -Q -G --double=24 --float=24 --rom=0-4FF --opt=tasm,tasmfile,-speed,+space,-debug,-local --c
mcc_generated_files/pic16f1_bootload.c:95: error: (984) type redeclared
mcc_generated_files/pic16f1_bootload.c:95: error: (1098) conflicting declarations for variable "MMIOIR" (mcc_generated_files/pic16f1_bootload.c:95)
(908) exit status = 1
nbproject/Makefile-default.mk:170: recipe for target 'build/default/production/mcc_generated_files/pic16f1_bootload.pl' failed
make[2]: Leaving directory 'D:/bootloader/16f18323bootloader.X'
nbproject/Makefile-default.mk:90: recipe for target 'build-conf' failed
make[1]: Leaving directory 'D:/bootloader/16f18323bootloader.X'
nbproject/Makefile-impl.mk:39: recipe for target 'build-impl' failed
make[2]: *** [build/default/production/mcc_generated_files/pic16f1_bootload.pl] Error 1
make[1]: *** [.build-conf] Error 2
make: *** [.build-impl] Error 2

BUILD FAILED (exit value 2, total time: 1s)
```