

您設計產品時的好朋友！



Forum: [8-bit PIC](#)

Topic: [PIC18F25K40 MCC 產生錯誤](#)

Subject: [PIC18F25K40 MCC 產生錯誤](#)

作者: [austin1211](#)

2018年08月13日 18:44:12

線上先進大家好，
我用 MCC 進入設定 PIC18F25K40 ，
只有設定，還沒開始寫程式，編譯就有下列錯誤，
可以指點一下，哪裡設定錯誤，
謝謝。

附加檔案：

擷取0813.JPG(152.67 KB)

```
Interrupt Module
Easy Setup
Output Notifications [MCC] Pin Manager: Grid View
MPLAB Code Configurator OCT0040V02 (Build, Load)
C:\Program Files\Microchip\xc8\v2.00\bin\xc8-cc.exe -mcpu=18f25k40 -c -no-short-double -no-short-loat -mem=wordwrite -UU -tasmfile -maddrqual=
In file included from mcc_generated_files/interrupt_manager.c:49:
mcc_generated_files/interrupt_manager.h:145:6: error: variable has incomplete type 'void'
void interrupt INTERRUPT_InterruptManager (void);
^
mcc_generated_files/interrupt_manager.h:145:15: error: expected ';' after top level declarator
void interrupt INTERRUPT_InterruptManager (void);
^
In file included from main.c:44:
In file included from ./mcc_generated_files/mcc.h:53:
./mcc_generated_files/interrupt_manager.h:145:6: error: variable has incomplete type 'void'
void interrupt INTERRUPT_InterruptManager (void);
^
./mcc_generated_files/interrupt_manager.h:145:15: error: expected ';' after top level declarator
void interrupt INTERRUPT_InterruptManager (void);
^
In file included from mcc_generated_files/mcc.c:47:
In file included from mcc_generated_files/mcc.h:53:
mcc_generated_files/interrupt_manager.h:145:6: error: variable has incomplete type 'void'
void interrupt INTERRUPT_InterruptManager (void);
^
mcc_generated_files/interrupt_manager.h:145:15: error: expected ';' after top level declarator
void interrupt INTERRUPT_InterruptManager (void);
^
mcc_generated_files/interrupt_manager.c:65:6: error: variable has incomplete type 'void'
void interrupt INTERRUPT_InterruptManagerHigh (void);
^
mcc_generated_files/interrupt_manager.c:65:15: error: expected ';' after top level declarator
void interrupt INTERRUPT_InterruptManagerHigh (void);
^
2 errors generated.
4 errors generated.
2 errors generated.
make[2]: *** [build/default/production/main.p1] Error 1
make[2]: *** Waiting for unfinished jobs....
make[2]: *** [build/default/production/mcc_generated_files/interrupt_manager.p1] Error 1
(908) exit status = 1
nbproject/Makefile-default.mk:175: recipe for target 'build/default/production/main.p1' failed
(908) exit status = 1
nbproject/Makefile-default.mk:168: recipe for target 'build/default/production/mcc_generated_files/interrupt_manager.p1' failed
make[2]: *** [build/default/production/mcc_generated_files/mcc.p1] Error 1
(908) exit status = 1
nbproject/Makefile-default.mk:147: recipe for target 'build/default/production/mcc_generated_files/mcc.p1' failed
make[2]: Leaving directory 'C:/Austin/ATCAGC/OCT0040FW/OCT0040V02_V2.01a2/OCT0040V02.X'
nbproject/Makefile-default.mk:90: recipe for target 'build-conf' failed
make[1]: Leaving directory 'C:/Austin/ATCAGC/OCT0040FW/OCT0040V02_V2.01a2/OCT0040V02.X'
nbproject/Makefile-impl.mk:39: recipe for target 'build-impl' failed
make[1]: *** [build-conf] Error 2
make: *** [build-impl] Error 2
BUILD FAILED (exit value 2, total time: 2s)
```

[MyConfig.zip](#) 大小: 15.22 KB; 下載次數: 26