

# 您設計產品時的好朋友！



Forum: [8-bit PIC](#)

Topic: near 指令使用(Access Bank)

Subject: near 指令使用(Access Bank)

作者: yjo159pl

2020年01月31日 09:33:19

請問各位前輩:

我目前採用C18, P18F45K80

```
#pragma idata access My_RAM
near ....
....
....
(變數宣告)
....
#pragma idata
```

目前透過MPLAB Watch 監看Access Bank已使用到的位址為:

022h~ 041h, 當我需要再新增下一個存在Access Bank的變數, 編譯後得知如下錯誤, 請問是否為程式內有其他地方已占用剩下的Access Bank的位置, 麻煩請指點, 謝謝

相關圖片, 資料如下 .zip

附加檔案:

---

[question.zip](#) 大小: 182.17 KB; 下載次數: 26

[error.JPG](#) (70.27 KB)

```
Ereuting: "C:\Program Files (x86)\Microchip\mplab18\3.47\bin\mcc18.exe" -p=18F45K80A"C:\Program Files (x86)\Microchip\mplab18\3.47\bin" "program_test.c" -f="program_test.o" -D__DEBUG-D__MPLAB_DEBUGGER_I
Ereuting: "C:\Program Files (x86)\Microchip\mplab18\3.47\bin\mcc18.exe" -p=18F45K80A"C:\Program Files (x86)\Microchip\mplab18\3.47\bin" "Config_Initial.c" -f="Config_Initial.o" -D__DEBUG-D__MPLAB_DEBUGGER_I
Ereuting: "C:\Program Files (x86)\Microchip\mplab18\3.47\bin\mcc18.exe" -p=18F45K80A"C:\Program Files (x86)\Microchip\mplab18\3.47\bin" "System_Initial.c" -f="System_Initial.o" -D__DEBUG-D__MPLAB_DEBUGGER_I
Ereuting: "C:\Program Files (x86)\Microchip\mplab18\3.47\bin\mplink.exe" -p=18F45K80A"C:\Program Files (x86)\Microchip\mplab18\3.47\bin" /r"C:\Program Files (x86)\Microchip\mplab18\3.47\bin\LKR" "C:\Program Files (x
MPLINK 5.00, LINKER
Device Database Version 1.17
Copyright (c) 1998-2013 Microchip Technology Inc.
Error - section 'HighInterrupt_isr_tmp' can not fit the section. Section 'HighInterrupt_isr_tmp' length=0x00000009
Errors :1

Link step failed.
```