

# 您設計產品時的好朋友！

---



[Forum: Wireless Product \(WiFi, Bluetooth, ..\)](#)

Topic: RN4871 容易變磚

Subject: Re: RN4871 容易變磚

作者: cyshay

2017年07月27日 12:26:33

Did you put a 10uF cap across VBAT and GND very close to the module? The cap is required for stability. Please give me the PCB and schematics to review if possible. Thanks.

Martin Shay