

您設計產品時的好朋友！



Forum: [8-bit PIC](#)

Topic: [PIC16F877使用方法\[驅動方式\]](#)

Subject: [Re: PIC16F877使用方法\[驅動方式\]](#)

作者: Cnyntg927

2018年04月29日 19:18:15

我加那兩行我的編譯器會錯誤

附加檔案:

2018-04-29 (8).jpg(106.59 KB)

A screenshot of a Windows command prompt window titled 'cmd.exe' showing the output of a compilation process. The window contains the following text:

```
Assertion failed!  
Program: C:\PROGRA~2\gputils\bin\gplink.exe  
File: gpcofflink.c, Line 190  
Expression: sym != NULL  
This application has requested the Runtime to terminate it in an unusual way.  
Please contact the application's support team for more information.  
D:\PIC_16F877>sdcc --use-non-free -mpic14 -p16f877 PIC_ShowSeg.c  
PIC_ShowSeg.c:16: error 20: Undefined identifier 'ANSELO'  
PIC_ShowSeg.c:17: error 20: Undefined identifier 'ANSELHO'  
D:\PIC_16F877>sdcc --use-non-free -mpic14 -p16f877 PIC_ShowSeg.c  
message: Using default linker script "C:\Program Files (x86)\gputils\lkr\16f877_g.lkr".  
D:\PIC_16F877>sdcc --use-non-free -mpic14 -p16f877 PIC_ShowSeg.c  
message: Using default linker script "C:\Program Files (x86)\gputils\lkr\16f877_g.lkr".  
Assertion failed!  
Program: C:\PROGRA~2\gputils\bin\gplink.exe  
File: gpcofflink.c, Line 190  
Expression: sym != NULL  
This application has requested the Runtime to terminate it in an unusual way.  
Please contact the application's support team for more information.  
D:\PIC_16F877>
```